

Wheel-Like Structure


Possible Derrick

Broken Navigation Pile

Possible Vessel Funnel

SHORELINE SURVEYS LTD Hydrographic - Geophysical - Topographic			
Moreford Hall, Moreton, Dorchester, Dorset DT2 8BA Telephone: +44 1305 848821 or +44 7950 038317 email@shorelinesurveys.com - www.shorelinesurveys.com			
TITLE: Multibeam Bathymetric Survey of Withern Wreck Site Langstone Harbour			
CLIENT: Langstone Harbour Board			
PROJECT: Withern Wreck Multibeam Survey			
Project No: J1674	Scale: 1:200	Date: 07.10.19	Surveyed by: PL,PC Drawn by: EF,PL Checked by: EF,GE
			DO NOT SCALE COPYRIGHT

MULTIBEAM SURVEY
 Coordinated in OSTN15 with Grids at WGS84
 Depths below Chart Datum (CD)
 CD taken as 2.74m below Ordnance Datum Newlyn (ODN)
 GPS and tidal data recorded by RTK GPS via VRS NOW
 Multibeam survey coverage sorted at 2 metre intervals using
 IHO rounding rules
 Survey coverage is not 100%
 Seabed mounted obstructions are not certainly detected
 Please refer to J1674_Report when reviewing this drawing

LANGSTONE

HARBOUR BOARD

